


**HEAT EXCHANGER AND CONDENSER TUBE INSPECTION**  
OUR HIGH SPEED "STATE OF THE ART" TUBE INSPECTION SYSTEMS


High Speed Eddy Current Inspection of Non-Ferrous Tubes

**The Problem**

Over the periods of their life, a proportion of tubes will suffer from erosion/corrosion, flaws in the material, as the tube wall thins or dependent on the type of cooling water and chemistry



**Typical Tube Defects**



**The Solution**

TEI's High speed eddy current system can detect even the smallest of defects at an average rate of up to 5 tubes per minute for a 10 meter condenser.

Our system uses compressed air to propel the eddy current probe through the tube at a rate of up to 6 meters per second. The computerized control system detects the end of the tube and automatically stops and reverses, being pulled back through the tube at a speed of up to 3 meters per second, whilst surveying the tube wall for defects and metal loss. The results are recorded using special software and are analyzed by our PCN level 2 inspector in real time.

**Data**

- ▶ Minimized inspection time leads to shorter outages.
- ▶ Probe insertion speeds up to 22ft/sec.
- ▶ Inspection of up to 8 tubes per minute (30ft/10m long).
- ▶ Uses a 4 frequency, simultaneous injection, ECT system with 8 standard channels along with multiple mixing channels.
- ▶ Using 4 frequencies eliminates false positives such as magnetic inclusions.
- ▶ I.D/O.D. defects are immediately distinguishable.
- ▶ Possible to inspect up to 2,000 tubes (10m long) in a normal working day using a single instrument.
- ▶ Manual and computer automated analysis is done on the spot.
- ▶ Final report includes coloured tube sheet maps.

High Speed Probe Pulling System



## Inspection of Ferrous Heat Exchanger and HP Heater Tubes

### The Problem

Over the period of their life, a proportion of Heater Tubes will suffer from erosion/corrosion, and tube wall thinning as a result of extreme temperature and pressure fluctuation, thermal cycling or water chemistry.

Generally, being of ferrous materials, NDT tube inspection in a timely manner during tight schedule shutdowns is not considered. This often leads to costly forced shutdown or reduction in load when leaks materialize.



### Solution 1.

TEI's DC Saturation Eddy Current Technique (MAGWAVE) was developed to quickly inspect ferromagnetic tubular materials from the bore of the tube.

This technique was derived on the basis of conventional ECT utilizing the same inspection system and an external DC power supply, and automated software

As with the Eddy Current system, there is an option of utilising air assist probe driving system (PD-6K) may be used in conjunction for high speed transporting of the probe.

By using four frequencies in a simultaneous injection mode, defects, such as: ID/OD pitting, baffle cutting, steam impingement and general wall thinning, can be detected and sized.

With this option, inspection speed of 3 feet per second, up to 100 tubes can be inspected within an hour using the high speed system.


MAGWAVE technique is not only effective in detecting general and localized wall thinning in carbon steel materials, but also in other ferromagnetic materials, such as Sea-Cure, SS-400 series and Duplex

### Solution 2.

The DinSearch 1-00 series modular equipment is specifically designed for the in-situ inspection of carbon steel tubes in heat exchangers, gas coolers and boilers, and has a range of larger inspection probes for use with larger diameter tubes.

The system uses an established and proven electro-magnetic technique which will detect pitting, general corrosion, wear under baffle plates and thinning caused by erosion or corrosion; the defect most commonly occurring in steel tubular heat exchangers and boilers.

It will detect internal and external defects, but like other tube inspection techniques, will not necessarily detect leaks. With typical tube material, the equipment will resolve 1mm diameter pits and 2% loss in wall thickness. Inspection probes are available for tube sizes from 16mm to 75mm o.d. (5/8" to 3" o.d.) and for the normal range of wall thicknesses encountered in boilers and heat exchanger tubes.



PO BOX 80 | CALDER VALE ROAD  
WAKEFIELD | UK | WF1 5YS

TEL: +44 (0)1924 780321  
FAX: +44 (0)1924 201901

yimpact@tei.co.uk  
www.tei.co.uk